

General Environmental Incident Summary

Incident: 4085 **Date/Time Notice:** 5/4/2016 1420 **DEM Incident No:**
Responsible Party: WBI Energy Transmission
Date Incident: 5/3/2016 **Time Incident:** 1530 **Duration:** 1 minutes
County: McKenzie **Twp:** 151 **Rng:** 98 **Sec:** 35 **Qtr:**
Lat: 47.85963 **Long:** -103.19090 **Method:** Interpolation from map
Location Description: From Watford City head north on HWY# 1806 approximately 4 miles. Turn right on 31 St NW and go 1/4 mile. Turn right and go 500 feet to pipe yard.
Submitted By: Greg Huncovsky **Affiliation:**
Address: 2010 Montana Ave.
City: Glendive **State:** MT **Zip:** 59330

Received By:

Contact Person: Greg Huncovsky
2010 Montana Ave.
Glendive, MT 59330

Distance Nearest Occupied Building: 500 Feet **Release Contained:** Yes

Type of Incident: Hydraulic Leak

Description of Released Contaminant: Hydraulic Fluid

Volume Spilled: 0.06 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

A small hydraulic leak developed on a sucker bucket in the pipe yard.

Risk Evaluation:

None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Contaminated soil was promptly removed and bagged for disposal. Further environmental impacts are highly unlikely.

Action Taken or Planned:

Diapers from a spill kit were used to wipe off the machine. Contaminated soil was removed and bagged for disposal. Crews will monitor equipment to ensure leaks do not persist.

Wastes Disposal Location: Waste will be stored on location in a sealed drum for the duration of the project. Upon project completion this waste, and contaminated soils from any other spills will be trucked to an approved landfill.

Agencies Involved:

Updates

Date: 5/5/2016 ***Status:*** Inspection

Author: Washek, Sandi

Updated Volume:

Notes:

Arrived on site at 5:37 p.m. Weather was sunny; temperature was 84 degrees F. I walked the pipeline storage area and the road surrounding the pipeline yard. No visible staining of ground material was noted. Photos were collected. No additional follow-up needed.

Date: 5/5/2016 ***Status:*** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Volume:

Notes:

According to the report, hydraulic fluid was released in a pipe yard. More follow-up needed.